

DM01-201 & DI32/DM32 & DE20

INSTRUCTIONS FOR INSERTING BATTERIES

Batteries are provided in a separate pack and must be inserted into the DM01 unit before it is turned on.

1. Insertion is easier if the DM01/DI32 unit is laid flat on its back.
2. Open the front cover by undoing the two screws located in the top and bottom right hand corners.
3. Locate and remove the four screws that hold down the battery cover.
4. Move the ends of the red interconnecting cable clear from the base of the box to allow the batteries to be placed.
5. Place the batteries back to back into the base with the terminals toward the top of the main box.
6. Connect the red interconnecting cable to the now bottom terminal on the left battery and the bottom terminal on the right battery. (i.e. the positive (red) terminal on the left battery and the negative (black) terminal on the right battery)
7. Connect the black cable to the top terminal (black) on the left hand battery.
8. Connect the red cable (with the fuse holder) to the top terminal (red) on the right hand battery.
9. Ensure the connectors are securely located.
10. Replace the battery cover by inserting and tightening the four holding screws.

INSTRUCTIONS FOR MOUNTING THE ENCLOSURE

DO NOT DRILL HOLES IN THE ENCLOSURE: Beneath each lid screw located in each corner of the enclosure, there are mounting holes which may be used to fix the enclosure. Penetrating the box will reduce its IP65 rating.